

FORM 124
1-64

EDITIONS

CLASSIFIED MESSAGE

DATE

0525Z 17 NOV 64

S E C R E T

ROUTING

1	CONMS	9
2		10
3	Eden	11
4	INTL	12
5	DIA	13
6	CC	14
7	RB	15
8		16

TO DIRECTOR

FROM [REDACTED]

ACTION:

INFO :

TOR 0623Z 17 NOV 64

FDD

RS

RP

RE

WC

LB

SR

PA

PB

ROUTINE

IN 57925

OYA 1-15 E

TO [REDACTED]

INFO

ONE [REDACTED]

6195

25X1A

FOLL IS SUMMARY OF BW MONITORING CONDUCTED AT [REDACTED]
FOR MISSIONS C264C AND 0054M:

25X1A

KCS USB

0030Z 6833 BEGAN MONITOR C264C
0015 ONE BURST. UNREADABLE. SIGS VERY WEAK, FOX
HAD TO BE TRIGGERED MANUALLY.
0312 9179 FREQ CHANGE, NO SIGNALS HEARD.
0402 14624 COMPLETED FREQ CHANGE. NO SIGNALS HEARD.
0458 CHIRP HEARD. UNREADABLE. TRIGGERED FOX MANUALLY.
0611 ONE BURST. UNREADABLE.
0612 9179 ONE CHIRP, NO 1 INV, A-OK.
0653 BELOW 60M, EGT BELOW 500 DEG, NO 1 INV, A.C. GEN OUT.
0655 BELOW 50M, EGT BELOW 325 DEG, NO 1 INV, A.C. GEN OUT.
0700 BELOW 40M. RPM BELOW 75 PER CENT.
0706 PRI AND SEC OXY OFF.
0715 AUTOPILOT DISENGAGED.

S E C R E T

GROUP 1
EXCLUDED FROM AUTO-
MATIC DOWNGRADING
AND DECLASSIFICATION

25X1A

[REDACTED] (IN 57925)

S E C R E T

PAGE TWO

0717 ONE CHIRP. FOX MANUALLY OPERATED. NO USABLE READOUT
OBTAINED.

0718 SECURED MONITOR

MISSION 0054 H:

0945 13269 BEGAN MONITOR

1001 THRU 1004 MANY CHIRPS RECEIVED. PARTIAL READOUT AS FOLLOWS.

1001 BELOW 40M, EGT 325-500 DEG, RPM BELOW 75 PERCENT,
80 KIAS AND LESS, NO. 1 INVERTER, A.C. GEN OFF,
OIL PSI 0 TO MINUS 5 AND BELOW.

1003 BELOW 60M, BELOW 40M, EGT ABOVE 500, NO. 1 INV.

1004 SAME AS ABOVE.

1021 ONE BURST. UNREADABLE DUE QRM. OPS ADVISED.
DRIVER CONTACTED ON UHF AND GIVEN OK TO CARRY ON.

1029 MONITOR SECURED TO BEGIN PACKING OF EQUIP.

END OF MESSAGE

S E C R E T